

## WARNING

### READ INSTRUCTIONS CAREFULLY BEFORE INSTALLING. KEEP THIS INSTRUCTIONS FOR FUTURE REFERENCE

Fixtures must be wired in accordance with the National electrical code and all applicable local codes. Proper grounding is required for safety.

**THIS PRODUCT MUST BE INSTALLED IN ACCORDANCE WITH THE APPLICABLE INSTALLATION CODE BY A QUALIFIED ELECTRICIAN WHO IS FAMILIAR WITH THE CONSTRUCTION AND OPERATION OF THE PRODUCT AND THE HAZARDS INVOLVED.**

**WARNING:** Risk of fire or electric shock. High bay Light installation requires knowledge of l uminares and electrical systems. If not qualified, DO NOT try to install.

Please contact an electrician.

**WARNING:** Risk of fire or electric shock. Suitable for wet locations. Make sure the power is off permier to install.

**WARNING:** Risk of fire or electric shock. Suitable for non-insulated surface and frame.

DO NOT cover fixture with insulation liner or similar material.


**WARNING:** DO NOT install in unstable, loose or breakable surfaces.

**WARNING:** DO NOT let objects impact or exert force on the surface of the fixture.

## SHOCK HAZARD!



Turn power OFF at circuit breaker prior to installation or servicing.




## TOOLS REQUIRED

Tools:

1. Sharp Side Cutter
2. Electric Drill
3. Level
4. Measuring Tool
5. Wire Stripper / Knife
6. Philips Screwdrivers
7. Wire Cutters


## WIRING

### CORD/ SUOOLY WIRING




## Ceiling mounted


1. Take the fixture and accessory out from cartoon box, tighten 2x angle holder screw as Fig.1.




2. Flexible metal conduit install and tighten with the fixture.



3. Drill 2x hole as Fig.2, the distance can be 91~140mm, fixing  $\varnothing 10$  expansion screws and bracket on ceiling.




4. Connect the AC cable, Black cable joins to L, white cable joins to N, green cable joins to grounding.




## Wall mounted


1. Take the fixture and accessory out from cartoon box, tighten 2x angle holder screw as Fig.1.




2. Flexible metal conduit install and tighten with the fixture.



3. Drill 2x holes as Fig.2, the distance can be 91~140mm, fixing Ø10 expansion screws and bracket on wall.




4. Connect the AC cable, Black cable joins to L, white cable joins to N, green cable joins to grounding.




## Pole mounted


1. Take the fixture and pole accessory out from carton box, tighten pole as Fig.1. (Linear pole)



2. Connect the AC cable to installation box, Black cable joins to L white cable joins to N green cable joins to grounding.



3. Install the installation box to the wall or ceiling as Fig.2. Tighten the pole to the box, and adjust the chain of balance.



4. Install the fixture to the pole after cable connecting.

